

LIBELED: 3-15-61, S. Dist. Ohio.

CHARGE: 501(c)—when shipped, the strength of the article differed from that which it was purported to possess; and 502(a)—the label statement "Thiamine HCl. 50 mg." was false and misleading.

DISPOSITION: 4-14-61. Default—destruction.

6598. Vitamin B complex with B₁₂. (F.D.C. No. 45109. S. No. 32-352 R.)

QUANTITY: 518 cartoned vials at Brooklyn, N.Y.

SHIPPED: 8-25-60 and 8-26-60, from Philadelphia, Pa.

RESULTS OF INVESTIGATION: Examination showed that the article contained approximately 17 percent of the declared amount of vitamin B₁₂.

LIBELED: 12-5-60, E. Dist. N.Y.

CHARGE: 501(c)—while held for sale, the strength of the article differed from, and its quality fell below, that which it purported or was represented to possess; and 502(a)—the label statement "Each cc. contains vitamin B-12 30 mcgms." was false and misleading.

DISPOSITION: 3-3-61. Default—destruction.

6599. Hemacombin-P tablets. (F.D.C. No. 45148. S. No. 8-731 R.)

QUANTITY: 2 drums, containing a total of 24,500 tablets, and 5 100-tablet btl., at Rensselaer, N.Y.

SHIPPED: 3-1-60, from Englewood, N.J.

RESULTS OF INVESTIGATION: The article in the bottles had been repacked from bulk stock which had been shipped as described above. Analysis showed that the article contained approximately 73 percent of the declared amount of dextro-amphetamine sulfate.

LIBELED: 11-18-60, N. Dist. N.Y.

CHARGE: 501(c)—while held for sale, the strength of the article differed from, and its quality fell below, that which it purported and was represented to possess; and 502(a)—the label statement "Dextro Amphetamine Sulfate 1.5 mg." was false and misleading.

DISPOSITION: 3-22-61. Default—destruction.

6600. Clinical thermometers. (F.D.C. No. 45414. S. No. 27-398 R.)

QUANTITY: 37 boxes of 12 thermometers mounted on cardboard carriers with 6 thermometers on each carrier, and 2 carriers in each box, at Minneapolis, Minn.

SHIPPED: 12-20-60, from New York, N.Y., by Chase Bottle & Supply Co.

LABEL IN PART: (On thermometer) "Serial Number * * * C. F. Anderson * * * Oral."

RESULTS OF INVESTIGATION: Examination of 24 thermometers showed that 3 failed to meet the requirements for accuracy specified in CS1-52, issued by the National Bureau of Standards of the Department of Commerce, when tested as described in CS1-52; 1 failed to meet the requirement for retreating index as specified in CS1-52; 2 failed to meet the requirements for construction as specified in CS1-52; and 4 had the minor construction defect of having triplicate serial numbers.

LIBELED: 2-9-61, Dist. Minn.

CHARGE: 501(c)—when shipped, the quality of the article fell below that which it purported and was represented to possess; and 502(a)—the labeling